
ASSEMBLY INSTRUCTION
8081-2951

angel cerdá

1PC

FIG. 1




Connect the cable connections
to socket nº4 and terminal nº2




1PC

FIG. 2



Screw step 1 onto part 1



1PC

FIG. 3

