



ASSEMBLY INSTRUCTION  
4154 - MLM611670- 2614

**AC angel cerdá**


A	B	C	D	E	F	G	H
1 PC	1 PC	2 PCS	1 PC	1 PC	1 PC	1 PC	5 PCS
I	J	K	L				
8 PCS	8 PCS	8 PCS	1 PC				




**FIG.  
1**



**FIG.  
2**



**FIG.  
3**



ASSEMBLY INSTRUCTION  
4154 - MLM611670- 2614



A	B	C	D	E	F	G	H
1 PC	1 PC	2 PCS	1 PC	1 PC	1 PC	1 PC	5 PCS
I	J	K	L				
8 PCS	8 PCS	8 PCS	1 PC				




FIG.  
4

