

ASSEMBLY INSTRUCTION

7218-2712



A	B	C	D	E	F	G
	 M8x19	 M8x20	 M5			
8 PCS	56 PCS	56 PCS	1 PC	4 PCS	4 PCS	2 PCS
H						
						
3 PCS						

FIG.
1





FIG.
2



A	B	C	D	E	F	G
	 M8x19	 M8x20	 M5			
8 PCS	56 PCS	56 PCS	1 PC	4 PCS	4 PCS	2 PCS
H						
						
3 PCS						

FIG.
3




FIG.
2

